

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,219,937 B2

Page 1 of 1

APPLICATION NO. : 10/792188

DATED : May 22, 2007

INVENTOR(S) : Manfred Stöber, Klaus-Jürgen Winter and Karl Zacharias

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1:

Line 66, "reassembly" should be --preassembly--.

Column 2:

Line 44, delete "is" before "axis".

Column 4:

Line 46, "FIGS. 1 and to 2" should be --FIGS. 1 and 2--.

Column 5:

Claim 3, Line 47, delete "," after "indentation".

Claim 7, Lines 56-57, "planar bearing surface comprises an axial needle roller bearing" should be --support element forms an upper shell of said axial bearing--.

Column 6:

Claim 16, Line 23, "tow" should be --two--.

Signed and Sealed this

Eighth Day of July, 2008



JON W. DUDAS
Director of the United States Patent and Trademark Office